



EQ3 keys without function repair

Heating thermostat does not respond to pressing a button and is not to be programmed. Open, flood sensors with contact spray.

Written By: Claudio montefalcone



INTRODUCTION

The heating thermostat EQ3 is programmable. For this, the three keys must function. After some time, dirt in the buttons seem to gather. The can be eliminated with contact spray



TOOLS:


- [T6 Torx screwdriver](#) (1)
 - [Contact Spray](#) (1)
-

Step 1 — EQ3 keys without function repair




- Remove thermostat from the radiator

Step 2




- Open screwdriver and separate housing parts - four screws with TX6.

Step 3




- Loosen the four screws of the board, pull board

Step 4




- Board turn. The three buttons are the problem.

Step 5



- flood sensors with contact spray and move.

Step 6



- Everything reassemble. Check finished

Arbeite die Schritte in umgekehrter Reihenfolge ab, um dein Gerät wieder zusammenzubauen.

